

MecArmy

SPX10 User Manual

MecArmy's new Tactical high performance flashlight

Primary Features

- Patented innovation tactical flashlight, with a new concept in switches that can be operated through 360 degrees in any angle
- Instant access to STROBE from ON/ OFF
- Uses CREE XM-L2 U3 LEDs, max output up to 1100 lumens
- FREE USB rechargeable 3400mAh 18650 battery, with Panasonic cell and built in Micro USB connector
- Momentary ON function, one-handed operation
- Charging and fully charged indicators for USB rechargeable battery
- Standard Micro USB Charging port, charges on any USB port
- Standard 1 inch body design, suitable for common gun mount
- 3 mode design, easily changed by 360 degree push High/Low/Med
- Specially designed tail and head for shock and impact resistance
- Detachable tactical ring and clip
- Compatible with any 18650 or 2x16340, 2xCR123A battery
- Anti-roll and antiskid body design
- Reverse polarity protection prevents damage from an incorrectly inserted battery
- Constructed from aero grade aluminum alloy, with HAIII hard-anodization
- IPX-8 water resistance

Specification

Emitter: CREE XM-L2 U3 LED

Output & Runtime

Mode/ Specification	High	Med	Low	Strobe
Output (Lumens)	1100	328	24	1100
Runtime	2.28h	5.33h	125h	
Peak beam intensity	12590cd			
Max beam distance	224m			
Impact resistance	1.5m			
Waterproof	IPX8 (underwater 2 meters)			

- Dimensions
Length: 134mm/ 5.28in
Head dimension: 26.5mm/ 1.04in
Body dimension: 25.4mm/ 1in
- Weight: 102g/ 3.6oz (Excluding battery)
- Battery: Micro USB rechargeable 3400mAh 18650 Li-ion battery (can be used with any 18650 battery or 2x16340, 2xCR123A battery)
- Working voltage: 3V-9V
- Accessories: User manual, unique MecArmy rechargeable 18650 Battery, holster, lanyard, tactical ring, clip, 3xO-rings


NOTICE: The above-mentioned parameters are approximate and may vary between flashlights, batteries and environments.

Operation

- From OFF: Fully click for ON
- From ON: Fully click for OFF
- From OFF: Lightly press and hold for Momentary-ON
- From ON/OFF: Lightly push from side/ 360°(>2 second) for STROBE
- From ON: Lightly push from side/ 360°(>1 seconds) to change modes (High-Low-Med-Cycle)

Charging

Carefully unscrew and take out the rechargeable battery, and connect a mini USB charging cable as shown in the diagram below



Charging Indicator

When charging, the battery indicator light turns red, when charging is complete, the battery indicator light turns green
No indicator light indicates that there is no load

WARNING:

- Do not point the light at human or animal eyes
- Do not look directly into the light when it is switched on
- Do not permit children to use the flashlight unsupervised

Maintenance

- Remove battery when stored for extended periods
- Replace and lubricate O-Rings as needed to maintain IPX-8 rating
- Every 6 months, thread should be wiped with a clean cloth followed by a thin coating of silicon-based lubricant

Warranty Service

- Guaranteed exchange up to 15 days after purchase: any defective product can be exchanged for a replacement through a local distributor/dealer within 15 days
- After 15 days: all defective products can be repaired free of charge for a period of 5 years from the date of purchase
- Lifetime workmanship guarantee: after the free maintenance period has expired, the maintenance service will charge for material expenses only, free of labor expenses.

ALTUN LIMITED

TEL: +86-755-23764109

FAX: +86-755-23760255

E-mail: info@mecarmy.com

Web: www.MecArmy.com

Address: Yikang Mansion, Huarong Road,
Dalang Street, Longhua District,
Shenzhen, China

CE RoHS  