

Hard Reset CUBOT Max

- 1. The device must be turned off, so hold down the **Power rocker** for a while.



2. Afterwards press and hold together **Volume Up** and **Power button** for a few seconds.



3. You can release held keys when you see an Android Robot.

4. To enter the Recovery Mode hold down the **Power key** for a short while.



5. In the next step use **Volume buttons** to select "**wipe data/factory reset**" and tap the **Power button** to confirm.



6. Afterwards choose "yes" from the menu, and accept it with **Power button**.



7. After a while accept option "reboot system now" using Power rocker.



8. That's all. The hard reset operation should be completed.